## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Original Corner established by J.L. Nowlin, Deputy Surveyor, in 1859 from which Tamarack 15" bears N80°E, 33 links; Fir 9" bears N82°W, 20 links.

No records of any subsequent survey.

Description of corner evidence found:

No evidence of any corner recovered after extensive search.

Corner established by proportion. Corner established by doubling distance from recovered 1/4 corner and E 1/16 corner. Ran traverse between two aforementioned corners. Computed distance 1305.792 ft. (19.7847 chains) at bearing N 89° 24' 30" E. Extended line and set section corner at 19.7847 chains N 89° 24' 30" E of E 1/16 corner.

Description of monument and accessories I established to perpetuate the original location of this corner. Set 2½" Berntsen A-1 Federal Monument for corner projecting 18" above ground. Corner sets 17' north of old section line road. Road makes a bend to the south at this point. Cap stamped:

Corner sets in tag alder brush. No trees available for BTs. Set 2 3/4" iron pipes with 2" brass caps for witness monuments projecting 18" above ground.

#2 - West 20 links, stamped: W/C E 20 lks.

#1 - North 30 links, stamped: W/C S.30 lks.

T36N R12E Sec.  $\frac{27,26}{34135}$ S498-1977

Dated at Rhinelander	, Wis., this.	9th	day of	August	, 19 <u>.77</u>
Signature Shilip Annsen.  County Surveyor, Registere	•		<u>-</u>	•	
Office of Register of Deeds, County of instrument was filed in this office for reco					
at 3:30 o'clock P. M. Lugent sotale	mul				112158

.Deputy