This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3) (a)(b)(c)(d)(e)(f)(g)(h)(i). An additional sheet may be added if necessary to confirm with said requirements.

244705

FILED ON:
12/26/2024 02:24 PM
CORTNEY BRITTEN CLEEREMAN
REGISTER OF DEEDS
FOREST COUNTY WI

PAGES: 1 INDEX#: G9

(a) Corner Location:

Coordinates Obtained By:

E 1/4 Corner Section 8

Network RTK / Direct Observations

Township 40 North

N: 713056.906

Range 14 East

E: 873554.349

Town of Alvin
County of Forest


(b) History of Original Corner:

Date of Survey: May, 1865

Original Surveyor: William Daugherty Original B.T.'s: 12" Sugar - N 24° W, 15 Links

6" Sugar - N 28° E, 47 Links

Corner ID: 4014082000




(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for establishing location. If reestablishing through lost corner proportionate methods, indicate all monuments, distances, and directions used to establish. Indicate type of monument and sign post found or set.

For corner history, see previous U.S. Public Land Survey Monument Record by Gary Pisoni, dated November 2, 1989.

09/17/2024 - I found and accepted a 2" dia. iron pipe with a G.L.O. cap 12" above grade at the corner location. I found one existing bearing tree and 2 USFS steel sign posts, and made three additional bearing trees to witness the corner as shown below.

(c)(d)(e) Plan view of corner with ties to at least four witnesses. If in disagreement with previously established corner, show the distances between the two corners and also indicate the tie to the disputed corner.



Magnetic Bearings
Not to scale
N

- Steel fence post w/ USFS sign found S02°E, 0.92' and N47°W, 2.45' from corner.
- * Distances to bearing trees are to nail in side.



Certification

I, Gregory S. Maines, Professional Land Surveyor No. 2729, hereby certify that the corner location on this record was referenced by me or under my direction and control and that this U.S. Public Land Survey Monument Record is complete to the best of my knowledge and belief. REF: 2024355

Milabert Wilters	07070
1	7
	J. C. P.

134843	
NUMBER	
DOCUMENT	

State	of Wisconsin
County of	Forest ss.
certify that of	on the 2nd day vember 19 86. I found the Northwest Section 16. Hereon; and that from this evidence d a new monument and accessories hereon to perpetuate the original
Resident wi	
Ric	ch Sloat
•	
	1 1 1 1 1
 -	SECTION 16 1
,	
	i i

		Blaz	ed and scribe		ıg new bēan	ring tree:			4
			White Spr	uce 7" ·		S.85 E.	11.52	feet	$\overline{\alpha}$
i	1	7							4
! !	1 I	÷			•				4
i	, , , , , , , , , , , , , , , , , , ,				'				
- - - - - - -	1								
i	1 1								
l ·	1								
SECTI	DN 16 ¦	Date	l atIro	on River, MI	Wis., this	2nd	day of No	vember	, 19
7	i	~ ~ _ '	<i>(</i>)						
1	·	Signa	ture <i>M.C.s.M.f.</i> (County	Surveyor, Registered	Land Surveyo	r, or other duly at	thorized official)	Registration N	o
1	l	Office	of Register of De	eds, County of	Forest		,	hereby certify tha	it the w
-	 	– – instry	ment was filed in	this office for reco	rd on the	18th	day of Mar	ch	198
· ·		at	o'clock	: M.					
1	1		Haul 2	Hochen Spen	mosz				
_	l +	*********		(Register of Deeds)					
1]	.,	Jaul 7	48chen fres					

LAND SURVEY MONUMENT U.S. PUBLIC RECORD

s.5°15'w.

Monument as described and in place, from which the following bear:

N.85°E.

s.80°w.

24"

Original Government Survey in 1865 by Wm. E. Daugherty. Dependent resurvey of 1924.

withouthe U.S. Forest Service found a $2\frac{1}{2}$ " diameter by 30" long iron pipe with a brass

Corner restored from remains of original bearing tree. Jean Resvick, a land surveyor

cap stamped: T40N, R14E, S8, S9, S16, S17, 1924, U.S. General Land Office Survey from

65.34 feet

23.6 feet

20.6 feet

1.0 feet

S.5 15'W.

s.80°w.

S.44°E.

65.34 feet

20.60 feet

0.8 feet

History of original corner establishment:

Description of corner evidence found:

Steel sign post

which the following bear:

GLO Elm

Spruce

Elm (GLO)

Spruce

Elm

Index No. J-9


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



District Ranger

Date

Survey requested by: