This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7:08 U.S. Public Land Survey Monument Record (3) (a)(b)(c)(d)(e)(f)(g)(h)(i).

The coordinate value shown has been verified by at least one of the following methods: 1) Comparison to a previously GNSS determined published value; 2) The value is the average of two or more GNSS observations at a markedly different time; 3) One or more distances were measured back to the GNSS observed corner from temporary GNSS observed offset locations.

247020

FILED ON:

10/21/2025 09:59 AM
CORTNEY BRITTEN CLEEREMAN
REGISTER OF DEEDS
FOREST COUNTY WI

PAGES: 1

Corner ID: 43413100000

A-E 7.08(3)(a) Identity of the corner:

SE Corner Section 10 WISCRS - Forest County
Township 34 North N: 521835.789 USFT
Range 13 East E: 851752.287 USFT
Town of Nashville Datum: NAD 83 (2011)

County of Forest GNSS Method: WISCORS VRS Direct Observation

Original Corner Information:

Original Surveyor: J.L. Nowlin

Original B.T.'s: Hemlock 16" - N41°E, 40 links

Date of Survey: October 1865 Cedar 12" - N50°W, 26 links

ument evidence, occupational evidence, testimonial evidence or any other materio

A-E 7.08(3)(b)(e)(f)(g) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered. Describe any discrepancy between the corner restored and any previously established location. State whether the corners was restored through acceptance of obliterated evidence, a found perpetuated location, or determined by proportionate methods.

10/28/1963 Restoration of Lost Original Government Survey Corner by Neal Sperhake indicates he set a 1" dia. iron pipe with a Kimberly Clark aluminum cap and made four new bearing trees. (See corner form for prior history and additional information).

05/03/1979 Thomas R. Arnott, CSM V2 P259 found pipe with aluminum cap.

04/15/2025 I found and accepted a 1-1/4" dia. iron pipe with a Kimberly Clark Corp 4" dia. aluminum cap stamped to identify the corner 6" above grade and two existing bearing trees. I made two additional bearing trees to witness the corner as shown below.

A-E 7.08(3)(c)(d)(e)(h) Plan view of corner with ties to at least four witnesses. If in disagreement with previously established corner, show the distances between the two corners and also indicate the tie to the disputed corner. Distances and directions to other PLSS used as evidence or for proportioning.

13" Cedar (Existing)
Set new nail

7" Maple (Made)

7" Maple (Made)

1-1/4" dia. iron pipe with
4" dia. alum. cap found.

White Birch (Made)

Bearings given to the nearest second are Forest County Grid all other bearings are magnetic



- * Vinyl "T" post 0.8' south of corner.
- * Distances to bearing trees are to nail in side with BT tag on tree.
- * Sketch is not to scale



A-E 7.08(3)(i) - Certification

I, Gregory S. Maines, Professional Land Surveyor No. 2729, hereby certify that the corner location on this record was referenced by me or under my direction and control and that this U.S. Public Land Survey Monument Record is complete to the best of my knowledge and belief.

State of Wisconsin County of FOREST	ss. RESTORATION OF LOST ORIGINAL GOVERNMENT SURVEY CORNER.	
I NEAL SPERHAKE	, do hereby certify that on the WENTH EIGHTH day of OCTOBER	
19 63, I established t EAST, Fourth Principal M	the NORTHWEST SECTION CORNER OF SECTION 14. TOWNSHIP 34 NORTH, RANG	E 13
2101, 2001 01. 111101 011 1.		bed hereo
History: This corner we the original	was established during the original survey of this township, as not field notes for the original survey of T34N-R13E, 4th. p.m.	ed in
	and accessories I established to perpetuate the location of the for the location of the corner I emplaced a:	is corner:
"KIMBERLY CLARK CORP.	REE FEET LONG, ONE INCH IN DIAMETER, WITH ALUMINUM CAP DENOTED AS, T34N 10, 11, 14, 15 R13E SPERHAKE RLS 463 10/28/63.	
The pipe is witnessed by		
Cedar 7 N 6 E Cedar 10 S 78 E	39 links. (SCRIBED S10 NBT). 20½ links. (SCRIBED S11 NBT). 36½ links. (SCRIBED S14 NBT). 26½ links. (SCRIBED S15 NBT).	
Description as to how c	corner was located: No evidence of the original corner is present. erience has proved that the original survey was so erratic in the that proportionate measurement cannot be relied upon. Charles B Elcho, Wisconsin, a retired forester for the State of Wisconsin, ally showed me an old cedar post which he claims he set in 1949 site of the original corner for 10, 11, 14, 15. From the post that an old Blazed line, about 60 years old as determined by counting rings on overgrown wound material, running to the north. Edges of the south and east check out exactly with the original field of the lieve this post marks the site of the original corner. Thus replaced the post with a pipe and cap as denoted above.	is area forth of person- at the here is the f swamps notes.
restored	Subscribed & sworn to before me this 25 day of Aug 1964 NOTARY FUBLIC, FOREST CO., WIS COM. EXPIRES 10/31/65	88957
	Resident witnesses	
	Dated at Crandon , Wisconsin, this 25 day of Ang , 19 64 .	_ _
·	Signature play of purhase	<u></u>
	Title Registered Land Surveyor Registration No. 463	
Surveyor's Seal	Office of Reg. of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record on the 25 day of Aug 19 64 PM and was filed in Book No. Page No. of County Records.	Index No.
	Signature anna Poterson Title Reg. of Deeds	C C