## 247229

FILED ON:

11/11/2025 03:52 PM CORTNEY BRITTEN CLEEREMAN REGISTER OF DEEDS

> FOREST COUNTY WI PAGES: 1

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record (3) (a)(b)(c)(d)(e)(f)(g)(h)(i).

The coordinate value shown has been verified by at least one of the following methods: 1) Comparison to a previously GNSS determined published value; 2) The value is the average of two or more GNSS observations at a markedly different time; 3) One or more distances were measured back to the GNSS observed corner from temporary GNSS observed offset locations.

A-E 7.08(3)(a) Identity of the corner:

E 1/4 Corner (MC) Section 15

Township 34 North

Range 13 East

Town of Nashville

**County of Forest** 

Original Corner Information:

GNSS Method: WISCORS VRS Direct Observation

Original Surveyor: J.L. Nowlin Date of Survey: October 1865

**WISCRS - Forest County** 

N: 519370.965 USFT

E: 851686.311 USFT

Datum: NAD 83 (2011)

Original B.T.'s: Tamarack 8" - N5°E, 25 links

Tamarack 12" - West, 32 links

Corner ID: 43413152000

A-E 7.08(3)(b)(e)(f)(g) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered. Describe any discrepancy between the corner restored and any previously established location. State whether the corners was restored through acceptance of obliterated evidence, a found perpetuated location, or determined by proportionate methods.

12/12/1963 Restoration of Lost Original Government Survey Corner by Neal Sperhake indicates he set a 1" dia. iron pipe with a Kimberly Clark Corp aluminum cap by single proportion and made two bearing trees. (See corner form for prior history and additional information).

08/14/1978 Thomas R. Arnott, Certified Survey Map Vol. 2, Pg. 220 found a pipe with an aluminum cap.

04/26/1979 Thomas R. Arnott, Certified Survey Map Vol. 2, Pg. 260 found a pipe with an aluminum cap.

08/26/2021 Thomas J. McGuire, Certified Survey Map Vol. 10, Pg. 84 found an iron pipe with aluminum cap.

04/15/2025 The original government survey notes indicates this as a 1/4 Sec/MC post. I found and accepted a 1-1/4" dia. iron pipe with a Kimberly Clark Corp 4" dia. aluminum cap stamped to identify the corner 18" above grade along with one bearing tree, not of record. I used a found iron pipe from Certified Survey Map Vol. 2, Pg. 220 and made three additional bearing trees to witness the corner as shown below.

A-E 7.08(3)(c)(d)(e)(h) Plan view of corner with ties to at least four witnesses. If in disagreement with previously established corner, show the distances between the two corners and also indicate the tie to the disputed corner. Distances and directions to other PLSS used as evidence or for proportioning. Bearings given to the nearest

4" Spruce (Made) 8" Spruce (Made) 584° 48' 55"W 110.05' (110.12') 1-1/4" dia. iron 7" Spruce pipe found (Made) 1-1/4" dia. iron pipe with 4" dia. aluminum cap found . 12" Maple (Existing not of record) Set new nail

second are Forest County Grid. All other bearings are magnetic



- Vinyl "T" post 1.3' north of corner.
- Distances to bearing trees are to nail in side with BT tag on tree.
- Sketch is not to scale



A-E 7.08(3)(i) - Certification

I, Gregory S. Maines, Professional Land Surveyor No. 2729, hereby certify that the corner location on this record was referenced by me or under my direction and control and that this U.S. Public Land Survey Monument Record is complete to the best of my knowledge and belief.

Lake

Lily

-		
State of Wisconsin  County of FOREST	ss. RESTORATION OF LOST ORIGINAL GOVERNMENT SURVEY COR	NER.
		MBER
13 EAST, Fourth Princi		
	as d	escribed herec
History: This corner the original	was established during the original survey of this township, as I field notes for the original survey of T34N-R13E, 4th. p.m.	noted in
Description of monume	nt and accessories I established to perpetuate the location	of this corner
At the point determine	ed for the location of the corner I emplaced a:	
GALVANIZED IRON PIPE, "KIMBERLY-CLARK CORP.	THREE FEET LONG, ONE INCH IN DIAMETER, WITH ALUMINUM CAP DENOTE T34N 4 BTWN. 14 & 15 R13E SPERHAKE RLS 463 11/	D AS, 12/63."
The pipe is witnessed	· · · · · · · · · · · · · · · · · · ·	
W. Birch 8 S 86° W. Birch 7 N 48°	TE $18\frac{1}{2}$ links. (SCRIBED $\frac{1}{4}$ S 14 NBT). W 22 links. (SCRIBED $\frac{1}{4}$ S 15 NBT).	
<b>O</b>	corner was located: No evidence of original corner present. by proportionate measurement. The section corners $\frac{1}{2}$ mile nor have been previously established with a distance of 74.89 cha them. Thus, set the quarter corner 37.44 $\frac{1}{2}$ chains from either on a straight line between them.	th and south ins between
O = Corner monument restored		
	Subscribed & sworn to before me this 25 day for the sworn to be fo	ug 1964 ·
v		88977
	Resident witnesses	
	Dated at Crandon , Wisconsin, this 25 day of Aug , 1964 .	<del></del>
•	Signature Real Sheep-le	
	Title Registered Land Surveyor Registration No. 4	<del></del>
	Office of Reg. of Deeds County of Forest	<del></del>
	I hereby certify that the within instrument was filed in	this B
	office for record on the 25 day of Aug 1964, and was filed in Book No. Page No.	this a
Surveyor's Seal	of County Records.	
	Signature anna leteram Title Reg. of Deeds	

43413157,000