!Attention!

This PLSS corner is in the process of being updated by Forest County. An updated Tie Sheet will be available for this corner soon.

Please contact Kayla at the Forest County Land Information Department for more information.

Contact Info:

715-478-1387 or Kayla.L@co.forest.wi.us

	R9-9680-5 (7/15/64) H. C. WILLER CO., MILWAUKEE 448643	
Ci	ERTIFIED LAND CORNER RESTORATION	1 ,
State of Wisconsin		
County of <u>Forest</u>	55.	
I found evidence of the No. No. Township 36 North	ntheast Section corner of Section, Range 16 East monument and access corner:	ction 13 Principal Meridian, as described
Survey in 1857 by Artemas (A Hemlock, 200, 5 58 W, 25 A Hemlock 180, N 320W, 17 Marinette County Survey in		33°E, 89 LKs. ", S 69°E, 51 LKs.
-	essories I established to perpetuate the crision ollowing new bearing trees for the Ma •92 ft. or 13.515 LKs. •60 ft. or 25.151 LKs.	
A Red Pille, 10", N OZ W, 5	SOOD IN OF SHOOLS LIKES	JEAN F. RESVICK
	43616126000	RHINELANDER, WIS.
	Resident witnesses	2000 2 0 15 00 00 00 00 00 00 00 00 00 00 00 00 00
	Dated at Rhinelander Wisconsi	in, this 18th day ofFebruary
Sec. 13	19.69 Signature Jean F. Resvick (County Surveyor, Registered Land Surveyor,	Title Cadestral Surveyor
	Surveyors Registration No. S-802.	DOCUMENT 96944
	Office of Register of Deeds Con	unty of Forest
	I hereby certify that the within instrument won the 26th day of August	<u>.</u>
Corner monument restored	I hereby certify that the within instrument w	as filed in this office for record 19.62, and was filed in Book

Township 36 North Range 16 East Section 13 Index No. J-25 Page No.

Page No.......of County Records. 8:30 AM.

142948

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).


(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

Corner Common to Sections 12 and 13, T36N-R16E, and Sections 7 and 18, T36N-R17E

Index Number J-25 (T36N-R16E)

Forest County, Wisconsin



- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
- 1857 Original post by Artemas Curtis, witnessed by 20 Hemlock S58W 25 1ks.; 18 Hemlock N32W 17 1ks.; 10 Hemlock N33E 89 1ks.; 22 Y.Birch S69E 51 1ks.
- 1937 Corner restored with 4" iron pipe and Marinette County Survey brass cap by Gould and Hammes from original evidence.
- 1968 Corner recovered by J. Resvick, S-802, who marked NBTs: R.Pine 11" S82°E 8.92'; R.Pine 8" S17°W 16.60'; R.Pine 10" N82°W 35.65'. (Forest County Document #96744)
- 1991 Coleman Engineering Company recovered monument and NBTs of record; established additional corner references.
- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.
- 1. 4" Iron pipe with Marinette County Survey brass cap stamped with corner position.
- 2. Red Pine 13" N81°W 35.72 feet.
- 3. Red Pine 13" S84°E 8.85 feet.
- 4. Red Pine 14" S18°W 16.62 feet.
- 5. Red Maple 5" NO5°E 17.83 feet.
- 6. Steel sign post Northwest 1.84 feet.

Register of Deeds

2. 6. 01. 3. 4. Eng.

43616120000

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Accepted found monument as true corner position.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
 - (2) Found perpetuated location.
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

Charles F. Clark, Rls 1767

(i) 1, COLEMAN ENGINEERING COMPANY

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

August 23, 1991

Signature

CERTIFICATE READY FOR FILING:

Active District Ranger

Date

CHARLES F.
CLARK
S-1767
NIAGARA
WI
SURVEYOR
SURVEYOR