## !Attention!

This PLSS corner is in the process of being updated by Forest County. An updated Tie Sheet will be available for this corner soon.

Please contact Kayla at the Forest County Land Information Department for more information.

Contact Info:

715-478-1387 or Kayla.L@co.forest.wi.us

Index	No	N	-	2	5

, ,	0.0.			
	} ss.		of Wisc	State County of
	North, Range al Meridian, this evidence d accessories the original	, 19.5 ortheast 24 , I urth Princi I that from	on the March the N Section 36 thereon; and a new mel hereon to	certify that of
			tnesses:	Resident wi
		) N 24	SECTI	
		i	i	1

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 24 and 19 at 80.00 chains, set Section post from which the following bear: Sugar, 12", S 38 W, 25 lks; Sugar, 18", N 47 W, 69 lks; Sugar, 15", N 61 E, 37 lks; Yellow Birch, 26", S 34 E, 30 lks.

In 1936 and 1937, Marinette County surveyors, F.P. Gould and B.F. Hammes found a hardwood post and 2" iron pipe and found the original bearing tree stumps; Replaced iron pipe with a 4"dia. iron post in concrete with a Marinette County brass cap from which the following bear: Elm 6" N 11 W 167.5 lks.

Description of corner evidence found:

Found the monument and assessories as described above: Steel sign post North 0.7 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees: (Measurements taken to nail in side of tree)

Sugar Maple	7"	N 44°E	27.80 feet
Sugar Maple	7 <b>"</b>	s 34°E	12.45 feet
Sugar Maple	8"	s 38°w	12.19 feet
Sugar Maple	8 11	n 40°w	18.81 feet
Steel sign pos	t	West	0.90 feet

Dated atIron River, MI	this	26th	dav of	May	
Signature (County Surveyor, Register Office of Register of Deeds, County of instrument was filed in this office for recat. 30 o'clock M.					
(County Surveyor, Register	red Land Surveyor, o	r other c	luly authorized off	icial)	
Office of Register of Deeds, County of	Jouest	····	<b>/</b>	I hereby o	ertify that the within
instrument was filed in this office for rec	ord on the	2022	day of	Maich	, 19 <i>.9/</i>
at / 30 o'clock M.					
***************************************		***********			

(Register of Deeds)

By Deputy

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

