!Attention!

This PLSS corner is in the process of being updated by Forest County. An updated Tie Sheet will be available for this corner soon.

Please contact Kayla at the Forest County Land Information Department for more information.

Contact Info:

715-478-1387 or Kayla.L@co.forest.wi.us

	ĕ
i	p
•	b
1	q
ĺ	
i	F

581

State	of	Wisconsin	1	SS.
County of	E	Forest		

I Gary L. Pisoni do hereby certify that on the 30th day of March 19 94, I found evidence of the East quarter corner of Section 24 Township 36, North, Range 16-17 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:	
•	
***************************************	***************************************

		1	
		1	1
	1	1	1
			•
	 	<u> 0 </u>	
l	I	1	1
	1	1	1
	LOEOTIA	, 1 N O 4	
	SECTIO	JN 24	
	i	i	† 🔻
	l	1	1
	1	1	1
	1 1	1	1
	1 1 <u>1</u>	 	
	1 1 <u>1</u>	! !	1 1
	! ! !	 - 	
	1 1 1 I	 - 	
	1 1 1 1 1	 - 	

Corner monument restored.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 24 and 19 at 40.00 chains, set Quarter Section post from which the following bear: Elm, 15", S 40°W, 31 lks; Sugar, 12", N 28°E, 28 lks.

In 1936 and 1937, Marinette County surveyors, F.P. Gould and B.F. Hammes set the Quarter corner on line and by single proportionate measurement between the Northeast and Southeast Section corners of Section 24. They set a 4" dia. iron post in concrete with a Marinette County brass cap.

Description of corner evidence found:

Found the monument as described above and assessories set by unknown persons:

Iron	bar	1"	s 41°E	7.64 feet
Iron	bar	1"	s 33°w	7.57 feet
Iron	bar	1"	и 38 ⁰ w.	24.50 feet

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees: (Measurements taken to nail in side of tree)

Basswood	7"	N 56 E	11.65 feet
Sugar Maple	16"	s 45°E	9.64 feet
Sugar Maple	5"	s 30°W	9.76 feet
Sugar Maple	13"	N 36°W	25.90 feet
Steel sign post		и 03 ⁰ Е	2.7 feet

Dated at	Iron	River,	MI	, W s., this	26th	day of	May	19
						•		ration No. S-1634
	(Cou	inty Survey	or, Registere	d Land Surveyo	or, or other o	luly authorized offic	ial)	
Office of R	egister of	Deeds, Co	unty of	houes	<i>T</i>	,,,f	I hereby cer	rtify that the within
instrument	was filed	in this offi	ce for reco	rd on the	204	day of	Masel	19 <i>91</i> .
at /: 30	.o'clock	<i>P</i>	M.					
	*****************	(Pagiet	or of Doods	***************				

By Jul Tombeure


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



any 10-2-95 Signature