!Attention!

This PLSS corner is in the process of being updated by Forest County. An updated Tie Sheet will be available for this corner soon.

Please contact Kayla at the Forest County Land Information Department for more information.

Contact Info:

715-478-1387 or Kayla.L@co.forest.wi.us

		U.S.	PUBLIC	LANU	SURVEY	MONUMENI	KECUF
•							
sconsin	١						

		G-	21	
Index	No.	G	- I	

County of Forest I William B. Cochrane , do hereby certify that on the 8th day of August , 19.83 , I found evidence of the West Quarter corner of Section 12							
of August 19.83, I found evidence of the West Quarter							
Township							
Resident witnesses:							
David Brownell							
· · · · · · · · · · · · · · · · · · ·							
SECTION 12							
Corper monument rectored							

Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by H.& J.L. Nowlin. North between Sections 11 and 12, 40.00 chains, set Quarter Corner post to Sections 11 and 12, from which the following bear:

Box Elder 22" N16°E no distance recorded Sugar 8" S 3°W 20 1ks.

Description of corner evidence found:

Fence line West, and old Hwy 139 bears North and South.

I accept the fence line West, and the Center-Line of Old Hwy 139 as the best available evidence for restoring the corner position.

No original corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the restored corner position, set a $2\frac{1}{2}$ " diameter aluminum pipe monument, 3 feet long, $3\frac{1}{2}$ feet in the ground, with an aluminum cap stamped: T38N R14E, S11, S12, 1983, S-1107. From which the following new blazed and scribed bearing trees bear:

Basswood (clump) 8" N30°E 62.59 feet
Double Basswood 12" S75°W 51.20 feet

Jated atHilles,	Wis., this	48 L D	day ot₩	<u>iarcn</u>	, 19.02
ignaturehilliam B. Cochram (County Surveyor, Registered	Title Land Survey	Land Survey	yor authorized officia	Registr	ation No.S-1107
Office of Register of Deeds, County of	Forest d on the	24th	day of	, I hereby cer April	tify that the within
t 1:00 o'clock P. M. Daul Aschenbres	mer		•		
(Register of Deeds)					

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(ii) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

8" Basswood (clump)
N30°E, 62.59 feet

Quarter Corner S11 S12

12" Double Basswood

(i) i, William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

S75°W, 51.20 feet

William B. Cochrane March 28, 1985

