õ

SHOWN AND DESCRIBED HEREON MERIDIAN, AND I RE-ESTABLISHED SAID CORNER SECTION 25, T 38 N, R 14 E, FOURTH PRINCIPAL EVIDENCE OF THE WEST QUARTER CORNER OF ON THE 18TH DAY OF JUNE 2025, I FOUND ACCORDING TO THE WISCONSIN STATUTES AS I, TIFFANY N. HEISEL, DO HEREBY CERTIFY THAT

PROFESSIONAL LAND SURVEYOR THIS 25TH DAY OF JUNE, 2025

Appleton, WI 54911-5754 100 West Lawrence Street, Suite 412

RIATIVITY BEYOND ENGINEERING (920) 731-3499 rasmith.com

WITNESSES TO CORNER LOCATION:

**NICHOLAS J. KREPLINE** 

TIFFANY N. HEISEL

2.5" FOREST COUNTY ALUM MON FOUND

O 1" IRON PIPE SET

GRAPHIC SCALE

(IN FEET)

۷,

USING RTK GPS

DRAFTED BY: COUNTY OF: TOWN OF:

Ĭ

38 N

R\_14\_E

WISCONSIN

ROSS FORES1

•

CORNER LOCATION

COORDINATES OBTAINED

WISCONSIN COORDINATE REFERENCE SYSTEM FOR FOREST COUNTY

EAST (X)

S:\5169807\dwg\5169807\_PLSS-Forest County.dwg \ 3814128

NAD83 (2011) COORDS.

634,211.50

888,979.12

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:


1.) 1865 - H.&J.L. NOWLIN, ORIGINAL GOVERNMENT SURVEY. NORTH BETWEEN SECTIONS 25 AND 26,40.00 CHAINS, SET SECTION CORNER POST TO SECTIONS 25 AND 26, FROM WHICH THE FOLLOWING BEAR: 20" DIVISION JOB #7115. PLAN DATED 9/2/47. HE SET A 2.5" DIA. ALUM. PIPE MON, 3' LONG, 30" IN THE GROUND 1983 - SEPT. 19TH, W. COCHRANE FOUND NO EVIDENCE OF THE ORIGINAL CORNER. CORNER POSITION FALLS IN HWY 139 AND WAS RESTORED USING THE MEASUREMENTS AS SHOWN ON THE STATE HIGHWAY SUGAR, S 86° W, 21 LINKS AND 12" SUGAR S 51° E 20 LINKS. WITH AN ALUMINUM CAP STAMPED: T38N, R14E, S25, S26, 1983, S-1107, WITH THE FOLLOWING TIES: 20" MAPLE

DESCRIPTION OF CORNER EVIDENCE FOUND

N63°E 129.82' AND POWER POLE #73-2574 N32°W 34.45'.

ON JUNE 18, 2025 RASMITH FOUND THE ALUMINUM MONUMENT SECTION CORNER AND THE POWER POLE TIE

FOUR ADDITIONAL IRON PIPE WITNESSES WERE SET AND TIED AS SHOWN



SURVE SURVE 104 MINGCONS MILL TIFF ANY S-3272 HEISEL

246176

FILED ON: 07/17/2025 02:00 PM CORTNEY BRITTEN CLEEREMAN REGISTER OF DEEDS

FOREST COUNTY WI

T-21 PAGES: 1

43814262000

SECTION: 25

## 43814242000

85

127908	
Number	
ument	

I S	PURLIC	IAND	SHRVFY	MONUMENT	RECORD

		T-	2	ł
Index	No	•	_	•
IIIUEX	IIU.			

State of Wisconsin ss.
County of Forest
I. William B. Cochrane , do hereby certify that on the 19th day of September , 19.83 , I found evidence of the West Quarter corner of Section 25  Township 38 , North, Range 14 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.
Resident witnesses:
.David Brownell
Tony Tillman
<u></u>
<del>SECTION-25;</del>

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by H.&J.L. Nowlin. North between Sections 25 and 26, 40.00 chains, set Quarter Corner post to Sections 25 and 26, from which the following bear:

Sugar 20" S86°W 21 1ks. Sugar 12" S51°E 20 1ks.

Description of corner evidence found:

No original corner evidence was recovered.

Corner position falls in Hwy 139, and was restored using the measurements as shown on the State Highway Division Job #7115. Plan dated 9/2/47

Description of monument and accessories I established to perpetuate the original location of this corner.

At the restored corner position, set a  $2\frac{1}{2}$  diameter aluminum pipe monument, 3 feet long, 30" in the ground, with an aluminum cap stamped: T38N R14E, 1/4, S25, S26, 1983, S-1107. Blazed and scribed the following new bearing trees:

20" N63°E 129.82 feet Maple 34.45 feet Power Pole #73-2574 N32°W

Dated at Hiles , Wis., this 26th day of March	19. <sup>85</sup>
Signature William B. Cochrone Title Land Surveyor Registrati	ion No. S-1107
(County Surveyor, Registered Land Surveyor, or other duly authorized official)	
Office of Register of Deeds, County of Forest I hereby certifications in this office for record on the 24th (lay of April at 1:00 o'clock P. M.  (Register of Deeds)	fy that the withing 1985

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Power Pole #73-2574 N32°W, 34.45 feet 20" Maple -N63°E, 129.82 feet S25 Quarter Corner S26



William B. Cochrane

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane